

USA

Supplementary Sheet to the Assembly Instructions for the BUDERUS Cast Iron Boiler »Lollar« GK 505

Subject: Modifications of assembly instructions
Edition: 03/84; No. 925 941
Section 3: "Assembly of boiler sections"
Page 11 to 15

Important: The double sided boiler sealing as well as the sealing cord "Tapafill" are no longer required.

From now on only **one side of the boiler section is sealed** by use of the new elastic "Teroson" sealing cord.

The "Teroson" sealing cord is inserted in the grooves of the front boiler section being turned towards the viewer during assembly.

The following instructions are no longer applicable:

- page 10: Fig. 10 - indication "Outer sealing cord",
- page 14: Fig. 14 - indication "Sealing cord" on the rear section.